




Technical drawing of a mechanical assembly, showing exploded views A and B, and a coordinate system.

View A: Shows the main assembly structure. Key components labeled include:

- 17.2b, 17.1, 17.2, 17.2a, 15.2a, 6.11, 17.1a, 15.3, 17.1b, 17.2c, 17.3, 6.1aB, 15.3a, 6.1B, 6.1, 6.1a, 15.2, 6.2, 6.2a, 7, 1, 18.1, 15.4, 15.4a, 18.1a, 6.2, 6.2a, 15.5, 18.1b, 18.3, 18.2, 26, 6.1B, 6.1aB, 15.5a.


View B: Shows a detail view of a component, likely a fastener or connector, with a coordinate system (x, y, z) indicating orientation.

A



Prior Art

Fig. 5



Prior Art

Fig. 6





Fig. 7

Prior Art



Prior Art

Fig. 8






Fig. 9


Prior Art



Prior Art

Fig. 10





Prior Art

Fig. 10A

Prior Art

Fig. 11




Fig. 12

Prior Art




Fig. 13





Fig. 14






Fig. 16 B

